


F11

LIB bearer tie down

Fix web stiffeners whenever connections are fitted to LIB and the top flange is not supported

Fix web stiffener and nail-on cleats to joist each side of pile to bearer tie down



2 nailon cleats per joist (one each side). Please refer fixing manufacturers specifications for nailing instructions